

INVENTÁRIO DO PATRIMÔNIO CULTURAL DO RIO GRANDE DO SUL
MINISTÉRIO DA CULTURA - IPHAN - 12º COORDENAÇÃO REGIONAL
GOVERNO DO ESTADO DO RS - SEDAC -IPHAЕ

1. MUNICÍPIO : Rio Grande
DENOMINAÇÃO : Vila Swift
ENDEREÇO : Honório Bicalho, Avenida N.º11-casa64
☒ URBANO ☐ RURAL

2	PRS/03-0007.00183
3.	TIPOLOGIA : 6- Arquitetura Civil Privada

4. ENTORNO :	OBS. :
HOMOGENEO DE EPOCA ☒	Faz parte do complexo da fábrica swift
HETEROGÊNEO ☐	
DESCARACTERIZADO ☐	

5. USO ATUAL :
☒ DESOCUPADO ☐ RUINA

7 . N.º DE PAVIMENTOS : 1	
☒ PORÃO	☐ SOTÃO
☐ OUTROS	

6 . FACHADA PRINCIPAL :	DATAÇÃO :																		
MATERIAL PREDOMINANTE : Tijolo a vista pintado																			
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 15%;">Verga</th> <th style="width: 15%;">RETA</th> <th style="width: 15%;">A. ABAT.</th> <th style="width: 15%;">A.PLENO</th> <th style="width: 15%;">A.OGIVAL</th> <th style="width: 15%;">OUTROS</th> </tr> </thead> <tbody> <tr> <td>JANELA</td> <td style="text-align: center;">X</td> <td style="text-align: center;">X</td> <td style="text-align: center;">—</td> <td style="text-align: center;">—</td> <td style="text-align: center;">—</td> </tr> <tr> <td>PORTA</td> <td style="text-align: center;">X</td> <td style="text-align: center;">—</td> <td style="text-align: center;">—</td> <td style="text-align: center;">—</td> <td style="text-align: center;">—</td> </tr> </tbody> </table>	Verga	RETA	A. ABAT.	A.PLENO	A.OGIVAL	OUTROS	JANELA	X	X	—	—	—	PORTA	X	—	—	—	—	
Verga	RETA	A. ABAT.	A.PLENO	A.OGIVAL	OUTROS														
JANELA	X	X	—	—	—														
PORTA	X	—	—	—	—														

9. ESTRUTURA :
Portante- alvenaria de tijolos.

8. COBERTURA :		TELHA CANAL	☐
N.º DE ÁGUAS : 4		TELHA FRANCESA	☐
COM BEIRAL	☒	TELHA DE ZINCO	☐
COM PLATIBANDA	☐	FIBROCIMENTO	☒

10. OUTROS ELEMENTOS EXTERNOS :

12. OBSERVAÇÕES :

Acesso principal com escadaria;
Jardim de inverno frontal;
Janelas guilhotina e de abrir.

11. SITUAÇÃO :

RUA ENG. HEKTOR AMARO BARCELOS

AL. HONÓRIO FRIOLO

RUA AURO

RUA AURO BOCK

RUA CHAVES

CAÇAVAN

SACO DA MANGUEIRA

13. FOTO :

A black and white photograph of a single-story brick building with a gabled roof. The building features large, multi-paned windows and a central entrance with steps. It is situated on a grassy field with trees in the background.

14. LOCALIZAÇÃO :

An aerial photograph of a residential neighborhood. The image shows several houses with reddish-brown roofs and green lawns. A red circle is drawn on the image, highlighting a specific location in the upper right quadrant. The circle is centered on a small, light-colored area that appears to be a driveway or a small clearing. The overall image has a slightly grainy, high-resolution quality typical of aerial photography.

15. TRATAMENTO DA ÁREA EXTERNA :

Isolada no lote com ajardinamento.

DATA : 11/06/2003

16. PESQUISADOR : Cássia